ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
10

Ward Name
Dodda Bommasandra

Street ID
W0160, W0241, W0237, W0089, W0197, W0162, W0193, W

Street Name
NA, Vinayaka Lyt 1st Crs, Vinayaka Lyt 2nd Crs, 4th Crs

Significant Landmark
Doddabommasandra

Segment No.
10/C-W0160/S022426

Total Length (m)
859.00

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	69.12	77.553594	13.062175	77.553476	13.061561	Blue moon garden	2nd cross
2	115.35	77.554022	13.063573	77.555079	13.063456	Blue moon garden	1st main road
3	87.21	77.557944	13.063920	77.558051	13.063139	Vinkatagiriyappa layout	4th cross
4	139.35	77.555932	13.062163	77.557216	13.062155	Raghavendra matt	1st Cross
5	23.92	77.556881	13.063188	77.557101	13.063172	Raghavendra matt	2nd cross
6	143.70	77.556848	13.063485	77.556818	13.062187	Raghavendra matt	4th cross
7	141.53	77.556547	13.062130	77.556399	13.060876	Raghavendra matt	3rd cross
8	138.82	77.556219	13.062135	77.556150	13.060980	Raghavendra matt	5th cross

Work Details

History of Road / Lane / Circles

Name of the Work
Package-3 Improvements to roads and drains providing ammenities construction of RO water plant Bangaluru one center providing sodium vapour lights sig

Sanctioned Estimated Amount (Rs.)
46880000

Sanctioned Year
2015-16

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Asphalting work

Job No. / Work Code
009-16-000052

Work Order No.
BBMP/EE/BTP/WO/50/2017-18

Work Order Date
06/01/2018

Period of Extention

Defect Liability Period From

	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
/01/2018	06/01/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
B.B.Umesh		0.00
Phone No.	**E-Mail ID**	
9886213563		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		basavaraj
Date of Inspection	**Remarks**	
29/05/2018		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R.L.Parameshwaraiah	29/05/2018	28/06/2018	As proposed
SE	Vasu K M	29/05/2018	28/06/2018	Verify
EE	Mohandas	29/05/2018	28/06/2018	verify
AEE	Shivakumar	29/05/2018	28/06/2018	Verify
AE	Basavaraj	29/05/2018	28/06/2018	Mobile verification is done
AE	Basavaraj	29/05/2018	28/06/2018	Forwarded

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0160, W0241, W0237, W0089,

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
11

Ward Name
Kuvempu Nagar

Street ID
W0250, I0196, W0339, W0337, W0301, W0319, W0188, W

Street Name
NA, Bimel Behind Rd, 11th Crs Lakshmi Sagar Lyt

Significant Landmark
Singapura village

Segment No.
11/C-W0250/S053602

Total Length (m)
623.07

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	197.45	77.535967	13.081234	77.534741	13.079925	Singapura lakkappa layout	cross road
2	179.54	77.535282	13.080531	77.536854	13.080022	Singapura lakkappa layout	cross road
3	187.17	77.535006	13.080268	77.536637	13.079714	Singapura lakkappa layout	cross road
4	58.91	77.536868	13.078726	77.536715	13.078219	Singapura varadarajaswamy temple	cross road

Work Details

History of Road / Lane / Circles

Name of the Work
PACKAGE 3IMPROVEMENTS TO ROADS AND DRAINS PROVIDING AMMENITIES CONSTRUCTION OF RO WATER PLANT BANGALURU ONE CENTER PROVIDING SODIUM VAPOUR LIGHTS SIG

Sanctioned Estimated Amount (Rs.)
46880000

Sanctioned Year
2015-16

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Asphalting

Job No. / Work Code
009-16-000052

Work Order No.
BBMP/EE/BTP/WO/50/2017-18

Work Order Date
06/01/2018

Period of Extention

Defect Liability Period From
06/01/2018

Defect Liability Period To
06/01/2020

Multiple road involved with the same Job No/ Work Code #
No

ractor Details

e of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
mesh		0.00
hone No.	E-Mail ID	
9886213563		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		gurusiddappa
Date of Inspection	**Remarks**	
29/05/2018		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R.L.Parameshwaraiah	29/05/2018	27/06/2018	As proposed
SE	Vasu K M	29/05/2018	27/06/2018	Verify
EE	Mohandas	29/05/2018	27/06/2018	verify
AEE	Shivakumar	29/05/2018	27/06/2018	Verify
AE	Gurusiddappa c gokale	29/05/2018	27/06/2018	Mobile verification is done
AE	Gurusiddappa C Gokale	29/05/2018	27/06/2018	Forwarded

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0250, I0196, W0339, W0337,